


OPERATION MANUAL

Please read these instructions before use and keep them where the operator may refer to them whenever necessary.


ADJUSTMENT OF BORING DIAMETER

Fig.1



- 1) Wipe the attaching surfaces of the ⑤ Shank body and the ① Cartridge thoroughly with a waste.
- 2) Put the ③ Belleville Spring through the ② Clamping Screw. (Fig.2)
Assemble the ① Cartridge on the head with the ② Clamping Screw. At this time, turn the wrench by finger to tighten the ② Clamping Screw, but the ① Cartridge must be able to move smoothly.
- 3) Turn the ④ Radial adjust screw, clockwise so that the ① Cartridge, is pushed out, and adjust the cutting edge to the requested boring diameter.
※ If the cartridge is moved too far turn the ④ Radial adjust screw counterclockwise, loosen the ② Clamping Screw, and push the ① Cartridge by finger in the direction where the boring diameter is smaller. After this, repeat 2) and the followings.
- 4) Tighten the ② Clamping Screw securely. Tightening torque 1.8N·m. (1.33 lbf·Ft)
- 5) Tighten the ④ Radial adjust screw again, and ensure that it is not loose.

Fig.2



If the radial adjust screw is loose, the screw may come out during cutting operation.

CAUTION

- Exchange the Clamping Screw and the Belleville Spring in proper period. In case that they are damaged and still used, it becomes quite hard to adjust the boring diameter, or the cartridge moves during cutting operation, which are very dangerous.
- In order to place an order of replacement parts, refer to the following table and indicate model No., part name and part No.

Replacement parts


Model No.	② Clamping Screw -2 pc. ③ Belleville Spring -2 pc.	③ Belleville Spring -4pc.	④ Radial adjust screw -5pc.
MW1619	MW16SS	MW16BS	H02503-5P
MW1821			H02504-5P

HOW TO SUPPLY COOLANT

MW shank body has 3 coolant holes. When the holes are plugged depending on the condition of boring operation, coolant can be supplied properly.


For boring a through hole

Plug a screw (M2.5×4L) into a center hole of the shank body as in the following figure. The amount of coolant to the cutting edges is increased.



For boring a blind hole

Plug screws (M2.5×4L) into 2 cross holes of the shank body as in the following figure. The central coolant supply evacuates chips more smoothly.



CAUTION

- At the first cutting, try several millimeters of boring and check whether chips are left in the hole. If the chips are left, there is a danger that chips may be jammed at cutting edges and break tools.
- The materials whose chips are easily jammed such as SS steel, low carbon steel and stainless steel, chips may not be evacuated.
- Supply emulsion type of coolant internally. Coolant pressure should be higher than 1.5MPa.
- Carbide shank type is exclusively designed for through-hole-boring.

ADDITIONAL CAUTION

CAUTION

- Since the insert clamping screw is expendable, exchange them periodically.
- Boring range of the boring head must not be exceeded.
- NEVER conduct boring under unsuitable cutting condition. For recommended cutting condition, refer to the catalogue.
- NEVER continue using the boring head, if it has suffered strong impact by bumping.
- Wear safety glasses during boring operation.
- NEVER exceed the maximum allowable spindle speed of 12,000 RPM.
This maximum allowable spindle speed is the limit value determined from the structure of the tool. It is not guaranteed to be applicable for actual boring.